

Power Line Hardware

FUSE CUTOUT CROSS REFERENCE GUIDE

PORCELAIN

<u>PLH</u>	<u>ABB</u>	<u>Chance</u>	<u>S&C</u>	<u>Cooper</u>
<u>15 kv (95 / 110 bil)</u>				
PLH-115-195PN	X1NCANAA11	C710-112PB	89021R9-CD	L4B1P1A
PLH-115-295PN	X1NCBNLA11	C710-114PB	89031R9-CD	L4BAP1A
PLH-215-395PN	X1NCBNPA21	C710-123PB	89071R9-CD	L4B2P1A
PLH-315-495PN	X1NCANCA31	C710-133PB	89221R9-CD	L4B3P1A
<u>27 kv (125 bil)</u>				
PLH-127-1125PN	X2NCBNAA12	C710-211PB	89022R9-CD	L9C1P1A
PLH-127-2125PN	X2NCBNMA12	C710-213PB	89032R9-CD	L9CAP1A
PLH-227-3125PN	X2NCBNBA22	C710-222PB	89072R9-CD	L9C2P1A
PLH-327-4125PN	X2NCBNDA32	C710-233PB	89222R9-CD	L9C3P1A
<u>27 kv (150 bil)</u>				
PLH-127-1150PN	X5NCBNAA12	C710-311PB	89042R9-CD	L9D1P1A
PLH-127-2150PN	X5NCBNMA12	C710-313PB	89052R9-CD	L9DAP1A
PLH-227-3150PN	X5NCBNBA22	C710-322PB	89092R9-CD	L9D2P1A
PLH-327-4150PN	X5NCBNDA32	C710-333PB	89223R9-CD	L9D3P1A

If Silicone :

CHANCE: Change C710 to CP710

S & C : Change R9 to R10-P